

Column1	Column2	Column3
		(PART 89-140)
AZ684020	AKA TBL4-LAMP	44HM84
		(PART 89-144)
223311083	TB25-LMP	46HM84
		46HM94
		46HM94P
		46HMX84
		52HM84
		52HM94
		52HMX84
		52HMX94
		62HM14
		62HM15
		62HM84
		62HM94
		62HMX84
		62HMX94
		(PART 89-146)
23311153	D95-LMP	45HM95
	23311127	46HM15
		46HM95
		46HMX85
		52HM195
		52HM85
		52HM95
		52HMX85

Column1	Column2	Column3
		52HMX95
		52MX95
		56HM195
		56HMX195
		56MX195
		62HM15
		62HM15A
		62HM195
		62HM85
		62HM95
		62HMX85
		62HMX95
		62MX195
		72HM192
		72MX195
		(PART 89-147)
72514011	Y66-LMP	
	REPLACED BY	
	75008204/Y67-LMP	
72514012	REPLACED BY 75007111	
72620067	D42-LMP	42HM66
75007111	REPLACED BY 75008204	
		(PART 89-148)
75007111	Y196-LMP	62HM116
		62MH196
		62MX195
		62MX196
		72HM196
		72MX196

Column1	Column2	Column3
		(PART 89-147)
75008204	Y67-LMP	50HM66
		50HM67
		50HMX96
		56HM15
		56HM16
		56HM66
		56HMX66
		56HMX96
		57HM167
		65HM117
		65HM167
		(PART 89-140)
72782309	TBL-4-LAMP	44HM85